Opened:	February 2, 2004			
For:	Installation of Automatic Fuel Tank Monitors			
			Petroleum Solutions, Inc.	United Pump & Supply
			retroleum Solutions, Inc.	United Fullip & Supply
04-019		MkR/mar	9907 Iota	505B Tradesman Park Drive
		T		
Item	Description	Quantity	San Antonio, TX 78217	Hutto, TX 78634
A.	Alamodome - 100 Montana			
	TLS 350 Monitor with printer	1	\$2,271.00	
	Four-Input probe module	1	\$382.00	-
	Two-Input/Two-Relay output module	1	\$151.00	
	Overfill Alarm	1	\$302.00	
	Overfill Alarm Acknowledgement Switch	1	\$187.00	-
	CSLD Software	1	\$733.00	· ·
	Magnetostrictive Probes (MAG 1)	1	\$977.00	-
	Magnetostrictive Probes Installation Kit	1	\$146.00	· ·
	Fax Modem	1	\$582.00	· ·
	Probe riser cap	1	\$44.00	\$50.00
	Total Installation Labor Cost		\$1,810.00	\$2,500.00
	Total Excavation Labor Cost		\$0.00	\$1,320.00
	Less Equipment Trade-In: NONE		\$0.00	
	Total Equipment Cost		\$5,775.00	\$6,175.00
	Total Alamodome Site Cost		\$7,585.00	\$9,995.00
D	EL 4 8 B. P. G			
В.	Fleet & Radio Services - 329 S. Frio		02.251.00	42.255.00
	TLS 350 Monitor with printer	1	\$2,271.00	
	Four-Input probe module	1	\$382.00	
	Eight-Input Module	1	\$582.00	-
-	Two-Input/Two-Relay output module	1	\$151.00	-
	Overfill Alarm	1	\$302.00	· ·
-	Overfill Alarm Acknowledgement Switch	1	\$187.00	-
	CSLD Software	1 2	\$733.00	· ·
	Magnetostrictive Probes (MAG 1)		\$1,954.00	
	Magnetostrictive Probes Installation Kit	2	\$292.00	
	Probe riser cap Interstitial FRP Sensor	2	\$88.00	
		2	\$408.00	-
	Interstitial 4" riser cap	2	\$90.00	\$100.00
	Total Installation Labor Cost		\$4,788.00	
	Total Excavation Labor Cost		\$0.00	
	Less Equipment Trade-In: TLS 250-1 Monitor		-\$700.00	
	Total Equipment Cost		\$6,740.00	\$8,240.00
	Total Fleet & Radio Services Site Cost		\$11,528.00	

Opened:	February 2, 2004			
For:	Installation of Automatic Fuel Tank Monitors			
			Petroleum Solutions, Inc.	United Pump & Supply
04-019	MkR/mar		9907 Iota	505B Tradesman Park Drive
			San Antonio,	Hutto,
Item	Description	Quantity	TX 78217	TX 78634
C.	Zarzamora Service Center - 4719 S. Zarzamora			
	TLS 350R Monitor with CSLD with printer	1	\$2,902.00	\$3,265.00
	Four-Input probe module	2	\$764.00	
	Eight-Input Module	1	\$582.00	
	Two-Input/Two-Relay output module	1	\$151.00	
	Overfill Alarm	1	\$302.00	
	Overfill Alarm Acknowledgement Switch Low voltage DIM module	2	\$187.00 \$390.00	
	CSLD Software (BIR version)	1	\$733.00	
	WPLLD Line Leak detectors	3	\$1,254.00	
	WPLLD interface module	1	\$182.00	
	WPLLD communications module	1	\$182.00	
	WPLLD controller module	1	\$182.00	\$200.00
	Risk Management Line Leak software	1	\$755.00	\$800.00
	Veeder Root Ethernet Modem Card	1	\$582.00	
	Magnetostrictive Probes (MAG 1)	5	\$4,885.00	
	Magnetostrictive Probes Installation Kit	5	\$730.00	
	Probe riser cap	5	\$220.00	\$250.00
	Total Installation Labor Cost		\$9,826.00	\$12,000.00
	Total Excavation Labor Cost		\$0.00	
	Less Equipment Trade-In: TLS 250 Monitor		-\$500.00	
	Less Equipment Trade-In: 5 Level Probes		-\$1,000.00	1
	Total Equipment Cost		\$13,483.00	\$15,505.00
	Total Zarzamora Service Center Site Cost		\$23,309.00	\$30,145.00
D.	Downtown Police Station - 214 W. Nueva			
	TLS 350R Monitor with CSLD with printer	1	\$2,902.00	\$3,265.00
	Four-Input probe module	1	\$382.00	·
	Eight-Input Module	1	\$582.00	\$600.00
	Two-Input/Two-Relay output module	1	\$151.00	
	Overfill Alarm	1	\$302.00	
	Overfill Alarm Acknowledgement Switch	1	\$187.00	
	Low voltage DIM module	1	\$780.00	
	CSLD Software (BIR version)	4	\$733.00	
	PLLD Line Leak detectors	1	\$1,254.00	
	Six-Input PLLD module	3	\$182.00	
	Three-Output PLLD module	1	\$364.00	
	Risk Management Line Leak software	2	\$755.00	
	Magnetostrictive Probes (MAG 1)	1	\$2,931.00	
	Magnetostrictive Probes Installation Kit	3	\$438.00	
	Veeder Root Ethernet Modem Card	1	\$582.00	
	Probe riser cap	3	\$132.00	
	Total Installation Labor Cost		Ø10.715.00	d11 000 00
-	Total Installation Labor Cost		\$10,715.00	
-	Total Excavation Labor Cost		\$0.00	
	Less Equipment Trade-In: TLS 250 Monitor		-\$500.00	
	Less Equipment Trade-In: 4 Level Probes		-\$600.00	
	Total Equipment Cost		\$11,557.00	
<u> </u>	Total Downtown Police Station Site Cost		\$22,272.00	\$31,020.00

Opened:	February 2, 2004			
For:	Installation of Automatic Fuel Tank Monitors			
			Petroleum Solutions, Inc.	United Pump & Supply
04-019	Y.		9907 Iota	505B Tradesman Park Drive
Item	Description	Quantity	San Antonio, TX 78217	Hutto, TX 78634
Е.	Northwest Service Center - 7000 Culebra Road			
	TLS 350R with CSLD with printer	1	\$2,902.00	\$3,265.00
	Four-Input probe module	2	\$764.00	\$800.00
	Eight-Input Module	1	\$582.00	
	Two-Input/Two-Relay output module	1	\$151.00	•
	Overfill Alarm	1	\$302.00	
	Overfill Alarm Acknowledgement Switch	1	\$187.00	
	Low voltage DIM module	2	\$390.00	
	CSLD Software (BIR version)	1 4	\$733.00 \$1,672.00	·
	WPLLD wireless leak detector WPLLD interface module	1	\$1,672.00	
	WPLLD controller module	2	\$364.00	
	WPLLD communication module	1	\$182.00	
	Risk Management Line Leak software	1	\$755.00	
	Magnetostrictive Probes (MAG 1)	5	\$4,885.00	
	Magnetostrictive Probes Installation Kit	6	\$876.00	\$990.00
	Interstital FRP sensor	1	\$204.00	
	Interstital Sensor Cap	1	\$45.00	
	Veeder Root Ethernet modem card Probe riser cap	1 6	\$582.00 \$264.00	
	1 tobe fiser cap	0	\$204.00	\$300.00
	Total Installation Labor Cost		\$8,607.00	\$12,000.00
	Total Excavation Labor Cost		\$0.00	
	Less Equipment Trade-In: TLS 250 Monitor		-\$500.00	
	Less Equipment Trade-In: 6 Level Probes Total Equipment Cost		-\$1,000.00 \$14,522.00	
	Total Northwest Service Center Site Cost		\$23,129.00	
	Total Portingest Bervier Center Bite Cost		Ψ23,127.00	ψ31,020.00
F.	Patrol North Police Substation - 13030 Jones Maltsberger Road			
	TLS 350R Monitor with CSLD with printer	1	\$2,902.00	\$3,265.00
	Four-Input probe module	1	\$382.00	·
	Eight-Input Module	1	\$582.00	
-	Two-Input/Two-Relay output module Overfill Alarm	1 1	\$151.00 \$302.00	
	Overfill Alarm Acknowledgement Switch	1	\$187.00	
	Low voltage DIM module	2	\$390.00	\$400.00
	CSLD Software (BIR version)	1	\$733.00	
	WPLLD wireless leak detector	2	\$836.00	
	WPLLD interface module	1	\$182.00	
-	WPLLD controller module WPLLD communication module	1	\$182.00 \$182.00	
	Risk Management Line Leak software	1	\$755.00	
	Magnetostrictive Probes (MAG 1)	2	\$1,954.00	
	Magnetostrictive Probes Installation Kit	2	\$292.00	\$330.00
	Interstital FRP sensor	2	\$408.00	
	Interstital Sensor Cap	2	\$90.00	
	Veeder Root Ethernet modem card	1 2	\$582.00	
	Probe riser cap		\$88.00	\$100.00
	Total Installation Labor Cost		\$4,918.00	
	Total Excavation Labor Cost		\$4,320.00	
	Less Equipment Trade-In: TLS 250 Monitor		-\$500.00	
	Less Equipment Trade-In: 2 Level Probes Total Equipment Cost		-\$400.00	
<del></del>	Total Patrol North Police Substation Site Cost		\$10,280.00 \$19,518.00	

For:	Installation of Automatic Fuel Tank Monitors			
			Petroleum Solutions, Inc.	United Pump & Supply
04-019		MkR/mar	9907 Iota	505B Tradesman Park Drive
Item	Description	Quantity	San Antonio, TX 78217	Hutto, TX 78634
G.	Patrol East Police Substation - 3635 E. Houston			
	TLS 350R Monitor with CSLD with printer	1	\$2,902.00	\$3,265.0
	Four-Input probe module	1	\$382.00	\$400.0
	Eight-Input Module	1	\$582.00	\$600.0
	Two-Input/Two-Relay output module	1	\$151.00	\$165.0
	Overfill Alarm	1	\$302.00	\$340.0
	Overfill Alarm Acknowledgement Switch	1	\$187.00	\$210.0
	Low voltage DIM module	3	\$585.00	
	CSLD Software (BIR version)	1	\$733.00	1-7
	WPLLD wireless leak detector	3	\$1,254.00	\$1,395.0
	WPLLD interface module	1	\$182.00	\$200.0
	WPLLD controller module	1	\$182.00	
	WPLLD communication module	1	\$182.00	
	Risk Management Line Leak software	1	\$755.00	
	Magnetostrictive Probes (MAG 1)	3	\$2,931.00	
	Magnetostrictive Probes Installation Kit	3	\$438.00	
	Veeder Root Ethernet modem card	1	\$582.00	
	Probe riser cap	3	\$132.00	\$150.0
	Total Installation Labor Cost		\$6,266.00	
	Total Excavation Labor Cost		\$2,656.80	
	Less Equipment Trade-In: TLS 250 Monitor		-\$500.00	
	Less Equipment Trade-In: 3 Level Probes		-\$600.00	
	Total Equipment Cost Total Patrol East Police Substation Site Cost		\$11,362.00 \$20,284.80	
	Total Fairoi East Police Substation Site Cost		\$20,284.80	\$20,473.0
I.	San Antonio Police Academy - 12200 SE Loop 410	1	¢2.002.00	\$2.265.0
	TLS 350R Monitor with CSLD with printer	1	\$2,902.00	
	Four-Input probe module	1	\$382.00	
	Eight-Input Module Two-Input/Two-Relay output module	1	\$582.00 \$151.00	
	Overfill Alarm	1	\$302.00	
	Overfill Alarm Acknowledgement Switch	1	\$187.00	
	Low voltage DIM module	1	\$195.00	
	CSLD Software (BIR version)	·	\$733.00	
	WPLLD wireless leak detector	1	\$418.00	
	WPLLD interface module	1	\$182.00	
	WPLLD interface module WPLLD controller module	1	\$182.00	
	WPLLD communication module	1	\$182.00	
	Risk Management Line Leak software	1	\$755.00	
	Magnetostrictive Probes (MAG 1)	1	\$977.00	
	Magnetostrictive Probes Installation Kit	1	\$146.00	
	Veeder Root Ethernet modem card	1	\$582.00	
	Probe riser cap	1	\$44.00	
	Total Installation Labor Cost		\$4,481.00	\$6,200.0
	Total Excavation Labor Cost  Total Excavation Labor Cost		\$0.00	
	Less Equipment Trade-In: TLS 250 Monitor		-\$500.00	
	Less Equipment Trade-In: 1 Level Probe		-\$300.00	1
			\$8,202.00	
	Total Equipment Cost	l l	(Q ')/(') / U	\$9,050.0

Opened:	February 2, 2004			
For:	Installation of Automatic Fuel Tank Monitors			
			Petroleum Solutions, Inc.	United Pump & Supply
04-019	MkR/mar		9907 Iota	505B Tradesman Park Drive
Item	Description	Quantity	San Antonio, TX 78217	Hutto, TX 78634
I.	Airport Maintenance - 10223 John Saunders			
	TLS 350R Monitor with CSLD with printer	1	\$2,902.00	\$3,265.00
	Four-Input probe module	1	\$382.00	\$400.00
	Eight-Input Module	1	\$582.00	\$600.00
	Two-Input/Two-Relay output module	1	\$151.00	
	Overfill Alarm	1	\$302.00	\$340.00
	Overfill Alarm Acknowledgement Switch	1	\$187.00	\$210.00
	Low voltage DIM module	1	\$390.00	
	CSLD Software (BIR version)	1	\$733.00	\$1,275.00
	PLLD Line Leak detector	2	\$836.00	\$930.00
	Six-Input PLLD module	1	\$182.00	
	Three-Output PLLD module	1	\$182.00	
	Risk Management Line Leak software	1	\$755.00	·
	Magnetostrictive Probes (MAG 1)	2	\$1,954.00	\$1,990.00
	Magnetostrictive Probes Installation Kit	2	\$292.00	·
	Veeder Root Ethernet modem card	1	\$582.00	
	Probe riser cap	2	\$88.00	\$100.00
	Total Installation Labor Cost		\$8,443.00	
	Total Excavation Labor Cost		\$0.00	
	Less Equipment Trade-In: TLS 250 Monitor		-\$500.00	
	Less Equipment Trade-In: 2 Level Probes		-\$400.00	1
	Total Equipment Cost Total Airport Maintenance Site Cost		\$9,600.00 \$18,043.00	
	•			, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
J.	Emergency Command Center - 115 Auditorium Circle			
	TLS 350 Monitor with CSLD with printer	1	\$2,271.00	
	Four-Input probe module	1	\$382.00	·
	Eight-Input Module	1	\$582.00	
	Two-Input/Two-Relay output module	1	\$151.00	
	Overfill Alarm	1	\$302.00	
	Overfill Alarm Acknowledgement Switch	1	\$187.00	·
	CSLD Software	1	\$733.00	
	Magnetostrictive Probes (MAG 1)	1	\$977.00	
	Magnetostrictive Probes Installation Kit	1	\$146.00	·
	Submersible pump sensor	1	\$126.00	
	Interstitial FRP Sensor Interstitial 4" riser cap	1	\$204.00	
	Veeder Root Ethernet modem card	1	\$45.00 \$582.00	
	Probe riser cap	1	\$44.00	
	·			
	Total Installation Labor Cost		\$2,416.00	
	Total Excavation Labor Cost		\$0.00	
	Less Equipment Trade-In: TLS 250 Monitor		-\$500.00	
	Less Equipment Trade-In: 1 Level Probe		-\$200.00	
	Total Equipment Cost		\$6,032.00	
	Total Emergency Command Center Site Cost		\$8,448.00	\$10,735.00
	Veeder Root Inform Software, Part # 848940-006		\$1,021.00	Not Giver
	1		Î.	1